

Search

FILE 'CAPLUS, WPIX' ENTERED AT 10:01:27 ON 19 AUG 2004

L1 710162 SEA ABB=ON PLU=ON ?GLASS?
L2 390226 SEA ABB=ON PLU=ON ?GLASS?
TOTAL FOR ALL FILES

L3 1100388 SEA ABB=ON PLU=ON ?GLASS?
L4 21475 SEA ABB=ON PLU=ON (?GLASS? (5A) (GROUND OR COMMINT? OR POWDER?))
L5 14919 SEA ABB=ON PLU=ON (?GLASS? (5A) (GROUND OR COMMINT? OR POWDER?))
TOTAL FOR ALL FILES

L6 36394 SEA ABB=ON PLU=ON (?GLASS? (5A) (GROUND OR COMMINT? OR POWDER?))
L7 2145 SEA ABB=ON PLU=ON L4 AND FILLER?
L8 2086 SEA ABB=ON PLU=ON L5 AND FILLER?
TOTAL FOR ALL FILES

L9 4231 SEA ABB=ON PLU=ON L6 AND FILLER?
L10 454 SEA ABB=ON PLU=ON L7 AND (THERMOSET? OR ?EPOX?)
L11 550 SEA ABB=ON PLU=ON L8 AND (THERMOSET? OR ?EPOX?)
TOTAL FOR ALL FILES

L12 1004 SEA ABB=ON PLU=ON L9 AND (THERMOSET? OR ?EPOX?)
L13 1 SEA ABB=ON PLU=ON L10 AND (?ROUND? (5A) (CORNER? OR EDGE?))
L14 1 SEA ABB=ON PLU=ON L11 AND (?ROUND? (5A) (CORNER? OR EDGE?))
TOTAL FOR ALL FILES

L15 2 SEA ABB=ON PLU=ON L12 AND (?ROUND? (5A) (CORNER? OR EDGE?))

L16 1 DUP REM L15 (1 DUPLICATE REMOVED)
D ALL RN

L17 0 SEA ABB=ON PLU=ON L10 AND (?RESPIR? (5A) ?GLASS?)
L18 0 SEA ABB=ON PLU=ON L11 AND (?RESPIR? (5A) ?GLASS?)
TOTAL FOR ALL FILES

L19 0 SEA ABB=ON PLU=ON L12 AND (?RESPIR? (5A) ?GLASS?)
L20 1 SEA ABB=ON PLU=ON L4 AND (?RESPIR? (5A) ?GLASS?)
L21 1 SEA ABB=ON PLU=ON L5 AND (?RESPIR? (5A) ?GLASS?)
TOTAL FOR ALL FILES

L22 2 SEA ABB=ON PLU=ON L6 AND (?RESPIR? (5A) ?GLASS?)
L23 2 DUP REM L22 (0 DUPLICATES REMOVED)
D 1-2 ALL RN

=>